.. [1] \*:... \* | 2,1 - 1 | (44)2.

25X1A

	REPRODUCTION PROHIBITED		ឬស្ទីស្ទា 🖚 ជាមា ។
02023			
	6	11	16
- 12	7	12	17
- 2	8	13	18
		14	19
	16	15	2ø
	1 2 3 4 5 5	1 6 2 7 3 8 9 9 4 9 9	1   6   11   12   13   14   15   15   15   15   15   15   15

25X1A SECRET Ø81751Z NOV 71 CITE 25X1A IDEAL IST 25X1A A. 8131A 3. 655

E. (1) FLAPS WOULD NOT RETURN FROM GUST UP, AILERONS OK. FLAP CONTROL C/B POPPED; TRIED TO RESET TWICE, WOULD NOT RESET. C/A -SALICED 3 BURNED WIRES NO. C48, C47, AND C45, LEFT WING STATION 265

REF BLUE PRINT RR47 REV 1 WING FLAP AND AILERON SHIFT.

(2) TRACKER HEATER OVERHEAT LIGHT CAME ON 1 HR AFTER T.O., BLOWER POSITION OX. TRIED HEATER BLOWER TWICE, BUT LIGHT CAME ON BOTH TIMES. C/A - REPLACED TRACKER HEATER BLOWER, S/N OUT 13R, S/N IN 34.

F THRU G. NONE.

5 NOV 1971-6.1

SECREI

16